

WALT TRUCKER CAPS

Product Care

To keep your Walt Gear Trucker Cap looking its best, follow these steps to preserve its color and shape over time.

Proper care will help maintain the vibrant colors and ensure longevity.

Washing Instructions:

Prepare a Gentle Cleaning Solution:

Fill a sink or basin with cool water.

Add a small amount of mild liquid detergent specifically designed for colored fabrics.

Avoid powdered detergents, as they may be too harsh.

Soak the Cap:

Submerge the cap fully in the soapy water and let it soak for 5-10 minutes. This will loosen dirt and oil, making them easier to remove.

Hand Wash Gently:

After soaking, lightly swirl the cap in the water to lift out impurities. Avoid wringing, twisting, or scrubbing the fabric to prevent damage.

Rinse Thoroughly:

Rinse the cap under cool running water until all detergent is removed. Check for any remaining spots and clean them gently as needed.

Dry with Care:

Pat the cap semi-dry with a clean towel, focusing on the edges. Let the cap air dry in a shaded area, away from direct sunlight, which can cause fading. Hanging is an ideal method to help retain its shape.

Reshape as Necessary:

Once completely dry, lightly roll the crown between your hands to reshape it, if needed.

By following these steps, you'll keep your Walt Gear Trucker Cap vibrant and well-maintained. Always use cool water and avoid direct heat to ensure long-lasting color and durability.